Approved For Release 2002/06/18: CIA-RDP84-00951R000400010039-7 I-lob

8 August 1955

HEMORANDUK POE	# <b>Inf</b> 5pag 25X1A9a	e, Maintenanc	e and Facility	Branch,	OL,
attention,	25X1A9a				
SUEJECT	water Leaks	ge - 350-26th	Street		

- 1. The thunderstorm of Sunday, 7 August, caused the drainpipe in the SW corner of Venit C, (IBM punched card file) 350-26th Street, to overflow or leak water into the vault. The amount of water taken in was negligible and fortunately this time there was no damage to the card files.
- 2. It has been only a weeks since PBS craws, responding to our call for assistance after heavy rains caused a fleeding of the vault, supposedly repaired the roof over the vault and completely scaled off this drain. In view of this fact it is particularly distressing to find that the vault still leaks.
- J. In the three years and five months that CCD has occupied the "Stadium" we have registered numerous complaints and PBS has made numerous attempts to alleviate this condition. We do not think it unreasonable to expect PBS to come up with a satisfactory solution to this problem after hi months of trying.
- 4. Since the next heavy rain may again cause a flooding of this area, this problem warrants immediate attention.

25X1A9a

Assistant Chief, Administrative Staff, CCD

Distributions

Orig. & 1 - Addressee 1 - Chief, MD/CD 1 - Admin./CD

OCD/EEH: jeh